



NIDEC OKK CORPORATION

8-10, KITA-ITAMI, ITAMI
HYOGO 664-0831 JAPAN
International Sales Department
TEL: (81)72-771-1143
www.nidec.com/en/nidec-okk/
E-mail: nokk.ovsd@nidec.com

NIDEC OKK A DIVERSIFIED MANUFACTURER OF MACHINE TOOLS

Specializes In:

Machining centers
Graphite cutting machining centers
Grinding centers
CNC Milling machines
Conventional milling machines
Total die and mold making systems
Flexible manufacturing cells and systems

NOTE :

NIDEC OKK reserves the right to change the information contained in this brochure without notice.
NIDEC OKK is not responsible to make changes to previously sold machines or accessories.
The machines in the photographs of this brochure may include optional accessories.

The export of this product is subject to an authorization from the government of the exporting country.
Check with the government agency for authorization.

NIDEC OKK USA CORPORATION
101 South Gary Avenue, Suite B, Roselle, IL 60172, U.S.A
TEL: (1)630-924-9000

NIDEC OKK Europe GmbH
HANSEMANNSTR 33 41468 NEUSS, GERMANY
TEL: (49)2131-29868-0
FAX: (49)2131-29868-41

NIDEC OKK Machinery (THAILAND) Co., Ltd.
KUMTHORN HOLDING BUILDING 2nd FLOOR 897-897/1 Rama 3
Road, Bangpongpan, YANNAWA, BANGKOK 10120 THAILAND
TEL: (66)2-683-2160-2
FAX: (66)2-683-2163

NIDEC OKK (SHANGHAI) CO., LTD.
12F, TOWER B, 100 ZUNYI ROAD, CHANG NING DISTRICT,
SHANGHAI, CHINA
TEL: (86)21-62700930
FAX: (86)21-62700931

HM SERIES



Horizontal Machining Center

HM SERIES

HM 400	HM 500S
HM 5100	HM 6000S
HM 6300	HM 8000S
HM 800	HM 1000S
HM 1000	HM 1250S



HM Series Horizontal Machining Centers

HM-series horizontal machining centers are built with Our's exceptional designs and provided with superior performance ensuring high-speed machining, rigidity, reliability, and chip evacuation. Heavy cutting capability is just one of the HM-series specialties achieved by incorporating a highly developed rigid box-shaped frame.


Add to that the implementation of only the best in high-speed motors, and extremely reliable ATC's (auto tool changer) and APC's (auto pallet changer) that deliver minimal chip to chip time, these machines truly merge maximum performance with proven production reliability.



**HM400
HM500S**

Main specifications


HM400/40, HM400/50
Travel X x Y x Z mm (in) = 630 (24.80)x620 (24.41)x710 (27.95)
Rapid traverse rate m/min (ipm) = 54 (2,126)
Pallet size square mm (in) = 400 (15.75)
HM500S/40, HM500S/50
Travel X x Y x Z mm (in) = 630 (24.80)x620 (24.41)x710 (27.95)
Rapid traverse rate m/min (ipm) = 54 (2,126)
Pallet size square mm (in) = 500 (19.69)
*/40:BT40 type, /50:BT40 type



**HM5100
HM6000S**

Main specifications

HM5100
Travel X x Y x Z mm (in) = 800 (31.50)x750 (29.53)x880 (34.65)
Rapid traverse rate m/min (ipm) = [Std] XZ: 75 (2953), Y: 60 (2362)
Pallet size square mm (in) = 500 (19.69)
HM6000S
Travel X x Y x Z mm (in) = 800 (31.50)x750 (29.53)x880 (34.65)
Rapid traverse rate m/min (ipm) = [Std] XZ: 75 (2953), Y: 60 (2362)
Pallet size square mm (in) = 630 (24.8)



**HM6300
HM8000S**

Main specifications

HM6300
Travel X x Y x Z mm (in) = 1050 (41.34)x900 (35.43)x1030 (41.34)
Rapid traverse rate m/min (ipm) = X-Z:75 (2953) Y:54 (2126)
Pallet size square mm (in) = 630 (24.8)
HM8000S
Travel X x Y x Z mm (in) = 1050 (41.34)x900 (35.43)x1030 (41.34)
Rapid traverse rate m/min (ipm) = X-Z:75 (2953) Y:54 (2126)
Pallet size square mm (in) = 800 (31.5)



**HM800
HM1000S**

Main specifications

HM800
Travel X x Y x Z mm (in) = 1400(55.12)x1100(43.31)x1050(41.34)
Rapid traverse rate m/min (ipm) = 48(1889)
Pallet size square mm (in) = 800(31.5)
HM1000S
Travel X x Y x Z mm (in) = 1400(55.12)x1100(43.31)x1000(39.37)
Rapid traverse rate m/min (ipm) = 48(1889)
Pallet size square mm (in) = 1000(39.37)



**HM1000
HM1250S**

Main specifications

HM1000
Travel X x Y x Z mm (in) = 1700(66.93)x1400(55.12)x1400(55.12)
Rapid traverse rate m/min (ipm) = 48(1889)
Pallet size square mm (in) = 1000(39.37)
HM1250S
Travel X x Y x Z mm (in) = 1700(66.93)x1400(55.12)x1240(48.82)
Rapid traverse rate m/min (ipm) = 48(1889)
Pallet size square mm (in) = 1250(49.21)

[Std] Standard equipment or function
[Opt] Optional equipment or function

CONTENTS

Main features	P01	ATC(Automatic tool changer) 15	Controller	P31
Features	P03	Powerful feeding 16	F31i-B..... 31	
Chip disposal 06		Accuracy 17	FAi 32	
High speed and heavy-duty cutting 07		Cutting capacity 18	Specifications	P33
Spindle power and torque diagram 09		Operations..... 19	HM400/HM500S 33	
Pallet table and APC 11		Maintenance 20	HM5100/HM6000S 35	
High precision structure..... 12		Standard and option list..... 21	HM6300/HM8000S 37	
Tool magazine 13		Option	HM800/HM1000S 39	
		P22	HM1000/HM1250S 41	
		Software 29		

HM400/HM500S

With more rigid construction than conventional models, responding to the needs to machining a wide range of products from iron and cast iron to mold and die parts.

Not only the rigidity but also spindle speed, rapid traverse, reliability and machining performance have been upgraded.

HM400/40 and HM500S/40 models come equipped with a 10000min⁻¹ spindle, with an output of 37/26/22kW (50/35/30HP) available in BT40 spindle taper, as well as the option for a 15000min⁻¹ or 20000min⁻¹ spindle. HM400/50 and HM500S/50 models have a standard spindle reaching 12000 min⁻¹, with an output of 30/25kW (40/34HP) available in BT50 spindle taper, with an optional 8000min⁻¹. Allows customers the best option for the job.

The unique clamp construction provides excellent sealing performance by clamping while increasing the internal pressure of the table, thus preventing the infiltration of coolant enhancing the durability of the machines.



High rigid linear roller guides are used for all axes of X, Y and Z.

Even in the long hours of machining, high accuracy is maintained during extend use via forced-core-cooled ball screws that held stable with a double anchoring method to suppress lost motion.

The fine-feed movement and the lost motion property have been improved. The circular cutting accuracy is also improved significantly.


HM5100/HM6000S HM6300/HM8000S HM800/HM1000S

Double the speed, rigidity, reliability, durability, etc. compared with the conventional machines enable high-speed and high-accuracy machining of wide-ranging materials including hard-to-cut materials such as ferrous and casting materials.

In addition to the high rigidity of the machine main unit, highly-rigid linear roller guides on the X, Y and Z axes generate a synergetic effect and improve further the cutting performance.

Increase in the rapid-traverse rates, ATC speed, table turning speed and APC speed has shortened the non-cutting time and improved production efficiency.


For the improved heavy-duty cutting performance, the machine has a BT50 large-diameter ø100mm (3.94") spindle and a 45/30/26kW (60/40/35HP) high-power motor.



Built-in Rotary Table (BRT) use a new mechanism of precision reduction-gear roller drive. This drive system achieved high speed table indexing and toughness against overload or impact.^{*1}

Pallet positioning and clamping
Use of taper cones ensures high accurate repeatability of pallet positioning and flatness of the pallet is secured by means of Nidec OKK's original design multiple-clamp method.^{*2}

Master pallet is available as option.^{*3}



HM6300/HM8000S

Characteristics

- * The machining time is significantly improved by increasing all of speeds.
- * The ball screws are core-cooled ball screws and double anchored.
- * Spindle is selectable from BT40 and BT50 according to the required machining.
- * One piece shutters are used for X and Z axes and avoids chips and coolant going to inside.

(only Z-axis shutter is one piece type for HM400/50 and HM500S/50.)

Characteristics

- * Linear roller guides are capable the six times more moment load than a conventional model.
- * BRT use the high speed and high rigid reduction-gear roller drive that is more than double the rigidity and clamping torque compared to a conventional model.^{*1}

Specifications	Spindle speed (min ⁻¹)	Type of tool shank	Spindle bearing inner diameter (mm)	Rapid traverse rate (m/min)
HM5100/HM6000S	12000	BT50	ø100 (3.94")	X:75 (2953) Y:54 (2126)
HM6300/HM8000S				X:75 (2953) Y:54 (2126)
HM800/HM1000S	8000			48 (1889 ipm)

*1: HM800/HM1000S and HM1000/HM1250S use worm shaft and worm wheel. *2: HM400/HM500S is using center-clamping method. *3: Master pallet is available only for HM5100/HM6000S.

HM1000/HM1250S

All HM models are highly effective in machining cast-metal and iron-based work pieces, including construction machinery parts, such as cylinder blocks with massive valves requiring maximum rigidity for custom tooling and large molds.

Adopting twin-ball-screw drives and synchronously control for the Y and Z axes, suppresses vibrations and improves machining quality.

Furthermore for severe heavy-duty cutting, a larger spindle bearing diameter of 120 mm (4.72") with maximum spindle speed of 8000 min⁻¹, high-power spindle motor of 37/30 kW (50/40HP) and high-torque motorized spindle of 1009 N·m (744 ft·lbs) is available as option on HM1000/HM1250S.



Characteristics

* HM1000 and HM1250S models standard spindle delivers 12000min⁻¹, with a bearing diameter of 100mm (3.94") and 30/25kW (40/34HP), 420N·m (310 ft·lbs) of torque.


*Twin-ball-screws for both Y-and Z-axes, aiding in vibration dampening yielding extended tool life. The design focus is reduction of machining time, while increasing precision, surface finish, and contouring accuracy. HM-series are proven in high production machining environments and are ready to cut aluminum to cast metals.



Z axis twin-ball-screw

The Z-axis shutters and B-axis are angled sharply, allowing for excellent chip evacuation. Furthermore, We added a solid Y-axis shutter to eliminate any problems previously caused from chips clogging on un-maintained slide rails.


Thorough chip processing measures



HM400/M500S

HM5100/HM6000S

Chips are flushed so that they fall into the troughs on both sides of the table. Then, the chips are flushed out with coolant supplied through the nozzles provided in the front-end section of each trough. The coolant and chips are collected in the chip tank in the rear part of the machine (Chip flow coolant *1). In place of the standard method that flushes out chips with coolant, you may use optional coil-type chip conveyor *2 to clear the troughs and to discharge chips through the outlet in the rear part of the machine.



Lift-up chip conveyor and chip-bucket are option.



The troughs are extended and chips at the setup station can be collected.



Chip flow coolant *1

Chips are discharged from the troughs to outside of machine by big volume of coolant.

*1: Standard for HM400/HM500S, HM800/HM1000S.

*2: Standard for HM5100/HM6000S, HM630/800S, HM1000/HM1250S.

Ceiling shower [Opt]*3

Coolant through nozzles on the ceiling i.e. ceiling shower can be provided optionally for prevention of chips from accumulating on fixtures and workpieces.

*3: Standard for HM5100/HM6000S.

26 nozzles for HM400/HM500S 50 nozzles for HM800/HM1000S
27 nozzles for HM5100/HM6000S 91 nozzles for HM1000/HM1250S
22 nozzles & coolant curtain for HM6300/HM8000S



HM400/HM500S



HM6300/HM8000S



HM1000/HM1250S

High Speed and Heavy-duty Cutting



HM400/HM500Ss' standard spindle specification is motorized spindle, maximum speed 10,000min⁻¹ with grease lubrication, BT40 and 37/26/22kW (50/35/30HP). Optional spindles 15,000min⁻¹ and 20,000min⁻¹ are oil-air lubrication.

Spindle Cooling




Circulating the temperature-controlled oil around the spindle housing minimize the spindle temperature fluctuation.

MS: Motorized spindle

Cutting data	
Machine model	HM400/40
Material	S50C
Tool	ø32 mm (1.26") Long end milling
Length of the tool from tool holder nose	130 mm (5.12")
Spindle speed	1300 min ⁻¹
Feed rate	6500 mm/min (256 ipm)
Depth of cut	0.5 mm (0.02")
Width of cut	20 mm (0.79")

Standard Spindle 10,000min⁻¹



The BT50 spindle that can rotate at 12,000 min⁻¹ ensures the output of 30/25 kW in the case of HM400/50, HM800 and HM1000 and 45/30/26 kW in the case of HM5100 and HM6300 and its bearing is lubricated with the oil-air lubrication method. You can select the appropriate spindle according to the required machining.


Spindle Cooling



The spindle bearings are oil-air lubricated. Circulating temperature controlled oil is in the groove around the spindle housing suppressing the growth of the spindle. Furthermore, Nidec OKK's unique radiant cooling system prevents the conduction of heat generated from the motor into the spindle.


Cutting data	
Machine model	HM6300
Material	S45C
Tool	Face milling
Spindle speed	650 min ⁻¹
Feed rate	1000 mm/min (39 ipm)
Depth of cut	6 mm (0.24")
Width of cut	100 mm (3.94")

Standard Spindle 12,000min⁻¹



The BT50 spindle rotating at 8,000 min⁻¹ and ensuring the output of 55/37/30 kW is available optionally for HM6300 and HM8000S. It provides high power at the low-speed range with the maximum torque of 1,202 Nm.

Cutting data	
Machine model	HM6300
Material	S45C
Tool	Face milling
Spindle speed	650 min ⁻¹
Feed rate	1100 mm/min (43ipm)
Depth of cut	6 mm (0.24")
Width of cut	100 mm (3.94")




HM800 / HM1000S Gear-drive spindle [Opt]

Max. torque: 1251N·m (923ft·lbs)

As an option to deliver more torque for machining of hard-to-cut materials, an 8000min⁻¹ high torque gear-drive spindle produces 1251 N·m (923 ft·lbs). Available on HM800/HM1000S.

Gear-drive spindle [Opt]



Power of tool clamp

MS spindle			
Machine model	Spindle speed 10000min ⁻¹	Spindle speed 15000min ⁻¹	Spindle speed 20000min ⁻¹
HM400/40, HM500S/40	1000N (2200lbf)	1000N (2200lbf) [Opt]	1000N (2200lbf) [Opt]

MS spindle		
Machine model	Spindle speed 12000min ⁻¹	Spindle speed 8000min ⁻¹
HM400/50, HM500S/50	16300N (3700lbf)	—
HM5100/HM6000S	16300N (3700lbf)	—
HM6300/HM8000S	16300N (3700lbf)	20600N (4600lbf) [Opt]
HM800/HM1000S	16300N (3700lbf) [Opt]	—
HM1000/HM1250S	16300N (3700lbf)	20600N (4600lbf) [Opt]

Gear spindle	
Machine model	Spindle speed 8000min ⁻¹
HM800/HM1000S	19600N (4400lbf) [Opt]




SPINDLE POWER AND TORQUE DIAGRAM


HM Series

FANUC


10000min⁻¹ [37/26/22kW(50/35/30HP) MS]




15000min⁻¹ [37/26/18.5kW(50/35/25HP) MS]




20000min⁻¹ [37/26/18.5kW(50/35/25HP) MS]




8000min⁻¹ [22 / 18.5kW(30/25HP) Gear]




8000min⁻¹ [37 / 30kW(50/40HP) MS]




8000min⁻¹ [55/37/30kW MS]



12000min⁻¹ [30 / 25kW(40/34HP) MS]



12000min⁻¹ [45/30/26kW(60/40/35HP) MS]



#40

		10000min ⁻¹	15000min ⁻¹	20000min ⁻¹
Spindle motor	FANUC	37/26/22kW (50/35/30HP) MS	37/26/18.5kW (50/35/25HP) MS	37/26/18.5kW (50/35/25HP) MS
HM400/40, HM500S/40		Standard	Option	Option

#50

		8000min ⁻¹			12000min ⁻¹	
Spindle motor	FANUC	22/18.5kW (30/25HP) Gear	37/30kW (50/40HP) MS	55/37/30kW MS	30/25kW (40/34HP) MS	45/30/26kW (60/40/35HP) MS
HM400/50, HM500S/50		—	—	—	Standard	—
HM5100/HM6000S		—	—	—	—	Standard
HM6300/HM8000S		—	—	Option	—	Standard
HM800/HM1000S		Option	—	—	Standard	Option
HM1000/HM1250S		—	Option	—	Standard	Option

— : not available

Table Indexing, Rotating Time and Accuracy

For the IT (Index Table) specification, the table index accuracy of 2.5 seconds is guaranteed by using the large-diameter curvic couplings.

For the BRT (Built-in Rotary Table) specification, that has a rotary encoder as standard equipment, the table index accuracy of 2.5 seconds is guaranteed.


Machine model	Type of table	Index and rotation time (per 90°)
HM400/HM500S	BRT	0.5 sec
	IT[Opt]	1.9 sec
HM5100/HM6000S	BRT	0.5 sec
	IT[Opt]	1.7 sec
HM6300/HM8000S	BRT	0.6 sec
	IT[Opt]	4.5 sec
HM800	BRT	1.2 sec
	IT[Opt]	5.5 sec
HM1000S	BRT	1.2 sec
	IT[Opt]	5.5 sec
HM1000/HM1250S	BRT	1.8 sec
	IT[Opt]	5.0 sec

IT: Index table BRT: Built-in-Rotary Table




Structure of BRT

Drive with new method
(HM400/HM500S, HM5100/HM6000S, HM6300/HM8000S)



Worm and worm wheel drive
(HM800/HM1000S, HM1000/HM1250S)



M400/HM500S, HM5100/HM6000S, and HM6300/HM8000S models incorporate a newly designed table with a highly rigid reduction gear in place of a conventional worm shaft and wheel. This gear has minimal backlash, holds up to impact, and performs table indexing accurately at higher speeds. HM800/HM1000S and HM1000/HM1250S models use large-diameter bearings backing Our's continuous improvements on rigidity.

Direct Turn APC (Automatic Pallet Changer)

The HM Series exploits the direct-turn APC unit consisting of only a pallet lift and turning mechanism. Fewer parts mean less downtime. HM1000 and HM1250S a table load of 5000kg (11000 lbs) is available as an option. All APC units have been built with expansion in mind whether it's a pallet pool or transfer system, flexibly supporting a variety of machining environments.



HM400 / HM500S



HM5100/HM6000S

Machine model	Pallet changing time*1	Max. loadable weight on pallet kg (lb)*2
HM400	9.5 sec	450 (992)
HM500S	9.5 sec	450 (992)
HM5100	10.0 sec	800 (1764)
HM6000S	10.0 sec	700 (1543)
HM6300	15 sec	1500 (3300)
HM8000S	15 sec	1400 (3100)
HM800	19 sec	2000 (4400)
HM1000S	21 sec	2500 (5500)
HM1000	32 sec/43 sec[Opt]	3000 (6600)/5000 (11000) [Opt]
HM1250S	35 sec/43 sec[Opt]	3000 (6600)/5000 (11000) [Opt]



*1: JIS regulation time *2: Uniformly distributed loading

High Precision Structure

Lubrication oil cooler unit



Core cooling ball screws and Double anchor pre-tension system



The double-anchoring method limits elongation of the ball screws and improves the minute-feed characteristics and the lowers lost-motion characteristics. Accuracy in round cutting has also been improved largely.


All models of HM-series use core cooling ball screws on the X, Y and Z axes. Circulation of cooling oil through the ball screws, around ball screw support housings and motor mounting surfaces reduces the thermal displacement and maintains accuracy during long machining time.

Double Anchored Core Cooling Ball Screw, and Linear Roller Guides

HM400/HM500S




HM6300/HM8000S



HM1000/HM1250S




Tool Magazine for BT40



Machine Model	HM400/40, HM500S/40		
Tool storage capacity ¹	L mm (in)	H mm (in)	D mm (in) ²
40 tools [Std]	1315 (51.77)	2380 (93.70)	ø160 (6.30)
60 tools [Opt]		3060 (120.47)	
80 tools [Opt]		3910 (153.94)	
120 tools [Opt]	1860 (73.23)	3145 (123.82)	
156 tools [Opt]		3910 (153.94)	
178 tools [Opt]	2405 (94.69)	3145 (123.82)	
232 tools [Opt]		3910 (153.94)	

*1: The number of tool storage capacity refers a total number including the tool installed in the spindle i.e. subtract one from the above for the actual number of storage capacity.
 *2: D shows the max. diameter of tool without tool in adjacent pot. It is ø82mm (3.23") when tool is in adjacent pot.




Restriction of tools

Machine model	Max. tool length	Max. diameter with tool in adjacent pot	Max. diameter without in adjacent pot	Max.weight of tool	Moment load
	mm (in)	mm (in)	mm (in)	kg (lb)	N-m (ft-lbs)
HM400/40, HM500S/40	400 (15.75) ¹	ø82 (3.23) ¹	ø160 (6.30) ¹	12 (26.5) ²	9.8 (7.2)


*1: It is loadable under the restriction. (Refer to P34)
 *2: required slow ATC speed.

Tool Magazine for BT50



Machine Model	HM400/50, HM500S/50 ¹			HM5100/HM6000S			HM6300/HM8000S			HM800/HM1000S			HM1000/HM1250S		
Tool storage capacity ²	L mm(in)	H mm(in)	D mm(in) ³	L mm(in)	H mm(in)	D mm(in) ³	L mm(in)	H mm(in)	D mm(in) ³	L mm(in)	H mm(in)	D mm(in) ³	L mm(in)	H mm(in)	D mm(in) ³
40 tools [Std]	1715 (67.52)	2975 (117.13)	ø250 (9.84)	1990 (78.35)	2915 (114.76)	ø300 (11.81)	2105 (82.87)	2915 (114.76)	ø300 (11.81)	2180 (85.8)	3375 (132.9)	ø270 (10.63)	2330 (91.7)	3650 (143.7)	ø270 (10.63)
60 tools [Opt] ⁴		4175 (164.37)			4115 (162.01)			4115 (162.01)			4335 (170.7)			4610 (181.5)	
80 tools [Opt]		3215 (126.57)			3155 (124.21)			3155 (124.21)			3615 (142.3)			3890 (153.2)	
116 tools [Opt]	2530 (99.61)	4175 (164.37)		2835 (111.61)	4115 (162.01)		2960 (116.54)	4115 (162.01)		2995 (117.9)	4335 (170.7)		3160 (124.4)	4610 (181.5)	
120 tools [Opt]		3215 (126.57)			3155 (124.21)			3155 (124.21)			3615 (142.3)			3890 (153.2)	
160 tools [Opt]	2850 (112.20)	4175 (164.37)		3275 (128.94)	4235 (166.73)		3275 (128.94)	4235 (166.73)		3295 (129.7)	4335 (170.7)		3445 (135.6)	4610 (181.5)	
176 tools [Opt]															
236 tools [Opt]															

*1: Tool storage capacity 40 tools is standard for HM400/50 & HM500S/50.
 *2: The number of tool storage capacity refers a total number including the tool installed in the spindle i.e. subtract one from the above for the actual number of storage capacity. (40,60-tool magazine)
 *3: D shows the maximum diameter of tool when without tool in adjacent pot. It is ø115mm (4.53") when tool is in adjacent pot.
 *4: The 60-tool magazines with magazines stand is standard for HM5100/HM6000S & HM6300/HM8000S.



Restriction of tools

Machine model	Max. tool length ¹		Max. diameter with tool in adjacent pot ¹	Max. diameter without in adjacent pots ¹	Max. weight of tool	Moment load
	Standard mm (in)	Option mm (in)	Standard mm (in)	mm (in)	kg (lb)	N-m (ft-lbs)
HM400/50, HM500S/50	400 (15.75)	—	ø115 (4.53)	ø250 (9.84)	25 (55) ²	29.4 (21.7)
HM5100/HM6000S	600 (23.62)	—	ø115 (4.53)	ø300 (11.81)	30 (66) ²	29.4 (21.7)
HM6300/HM8000S	600 (23.62)	—	ø115 (4.53)	ø300 (11.81)	30 (66) ²	29.4 (21.7)
HM800/HM1000S	500 (19.69)	600 (23.62)	ø115 (4.53)	ø270 (10.63)	25 (55) ³	29.4 (21.7)
HM1000/HM1250S	600 (23.62) ⁴	—	ø115 (4.53)	ø270 (10.63)	25 (55)	29.4 (21.7)

*1: It is loadable under the restriction. (Refer to P34, P36, P38, P40, P42) -: not available
 *2: Required slow ATC speed.
 *3: 30kg (66lbs) for the gear head spindle
 *4: When three or more multiple magazines, 600mm (23.62") length tools are usable in the first and second magazines. In the 3rd or the following magazines, the maximum tool length shall be limited to 500mm (19.69").



Use of the Nidec OKK's proven and original high-speed synchronous tool changer (Nidec OKK patented) provides a steady tool change and excellent durability. In order to realize the smooth tool change operation, the standard specification includes the variable ATC function and, when the ATC handles the tool such as the heavy tool and the large-diameter tool, the ATC turning speed slows down automatically if the slow turning is selected at the time of tool registration.

BT40



Max.time the farthest position to waiting position of magazine					
40-tool magazine base		60-tool magazine base		80-tool magazine base	
40-tool	9.1 sec	60-tool	13.0 sec	80-tool	16.5 sec
—	—	120-tool	26.7 sec	156-tool	31.3 sec
—	—	178-tool	36.2 sec	232-tool	47.1 sec

Tool change time (cut to cut)	
Machine model	Standard
HM400/40, HM500S/40	3.3 sec

BT50




Max.time the farthest position to waiting position of magazine			
40-tool magazine base		60-tool magazine base	
40-tool	10.0 sec	60-tool	13.5 sec
80-tool	30.3 sec	116-tool	37.3 sec
120-tool	33.2 sec	176-tool	40.2 sec
160-tool	34.2 sec	236-tool	41.2 sec

Except HM5100/HM6300.

Tool change time (cut to cut)		
Machine model	Standard	Gear-drive spindle
HM400/50, HM500S/50	4.2 sec	—
HM5100/HM6000S	3.6 sec	—
HM6300/HM8000S	4.0 / 3.9 sec	—
HM800/HM1000S	5.8 sec	6.0 sec
HM1000/HM1250S	6.2 sec	—

--: not available

Slant structure (only for HM5100 / HM6000S / HM6300 / HM8000S)



HM5100/HM6000S

The slant structure of the X-axis guide mounting section reduces weight of the column and improves the acceleration performance without diminishing rigidity of the machine.



HM6300/HM8000S


Ball screw and lubrication method

Ball screws and feed guides are lubricated with grease to reduce the environmental loads.



Pallet positioning and clamping

Use of taper cones ensures high accuracy in repeated positioning of the pallets. Flatness of the pallet is secured accurately by means of the multi-clamp method. (HM400/HM500S use center clamp method.)




HM400/500S is center-clamp types

Soft scale II m [Spindle thermal displacement compensation function]


Thermal displacement of the spindle can be a cause for fluctuating machining accuracy. The soft scale II m reduces thermal displacement of the spindle and provides stable machining accuracy. The soft scale II m constantly monitors a rotating status of the spindle and temperature of the spindle and the machine body in order to compensate automatically the thermal displacement according to changes in machine movement and based on the accumulated Nidec OKK's original data.

Spindle thermal displacement

Y axis




Z axis



Cutting data	
Spindle speed	0-12000 min ⁻¹
Room temperature	21°C (±1°C)
Total running hours	60 hours included warming up time

* Due consideration should be taken for the machine installation status, environmental temperature and operating condition. The data here may not be obtained due to these conditions.

Accuracy of roundness





Roundness	Tolerance	Actual data example
HM400/HM500S	15µm (0.00059")	3.6µm (0.00014")
HM5100/HM6000S	15µm (0.00059")	3.8µm (0.00015")
HM6300/HM8000S	15µm (0.00059")	3.3µm (0.00013")
HM800/HM1000S	15µm (0.00059")	4.5µm (0.00018")
HM1000/HM1250S	15µm (0.00059")	5.0µm (0.00020")

Data condition	
Material	Aluminum
Cutting dia	250mm (9.85")
Feed rate	F500mm/min (19.7in/min)

- Notes:
- The data show example which obtained in short run. It may differ from data obtained in continuous run.
 - The data were obtained under Nidec OKK's test cutting conditions. The data may differ due to conditions of cutting tools, fixtures, cutting speed and room temperature.
 - The above accuracy are subject to machine installed according to Nidec OKK specifications and constant temperature environment. Accuracy are based on Nidec OKK inspection standard.


Cutting data



Face milling	Material: S45C					
	HM400/40, HM500S/40 ø100mm (4") x5 - tooth	HM400/50, HM500S/50 ø125mm (4.9") x6 - tooth	HM5100/HM6000S ø125mm (4.9") x6 - tooth	HM6300/HM8000S ø125mm (4.9") x6 - tooth	HM800/HM1000S ø125mm (4.9") x6 - tooth	HM1000/HM1250S ø125mm (4.9") x6 - tooth
Spindle speed	600 min ⁻¹	600 min ⁻¹	600 min ⁻¹	650 min ⁻¹	680 min ⁻¹	300 min ⁻¹
Cutting width	80 mm (3.15")	100 mm (3.94")	100 mm (3.94")	100 mm (3.94")	100 mm (3.94")	100 mm (3.94")
Cutting depth	5 mm (0.20")	6 mm (0.24")	6 mm (0.24")	6 mm (0.24")	6 mm (0.24")	6 mm (0.24")
Feed rate	800 mm/min (31 ipm)	800 mm/min (31 ipm)	1000 mm/min (39 ipm)	1000 mm/min (39 ipm)	1000 mm/min (39 ipm)	1000 mm/min (39 ipm)
Cutting amount	320 cm ³ /min (19.5 in ³ /min)	480 cm ³ /min (29.3 in ³ /min)	600 cm ³ /min (36.6 in ³ /min)	600 cm ³ /min (36.6 in ³ /min)	360 cm ³ /min (22.0 in ³ /min)	600 cm ³ /min (36.6 in ³ /min)
Spindle motor load	98%	107%	92%	93%	120%	115%

End milling on side	Material: S45C					
	HM400/40, HM500S/40 ø32mm (1.26") x6 - tooth	HM400/50, HM500S/50 ø50mm (1.97") x6 - tooth	HM5100/HM6000S ø50mm (1.97") x6 - tooth	HM6300/HM8000S ø50mm (1.97") x6 - tooth	HM800/HM1000S ø50mm (1.97") x6 - tooth	HM1000/HM1250S ø50mm (1.97") x6 - tooth
Spindle speed	250 min ⁻¹	160 min ⁻¹	160 min ⁻¹	160 min ⁻¹	160 min ⁻¹	160 min ⁻¹
Cutting width	25 mm (0.98")	20 mm (0.79")	20 mm (0.79")	25 mm (0.98")	30 mm (1.18")	30 mm (1.18")
Cutting depth	20 mm (0.79")	40 mm (1.57")	40 mm (1.57")	40 mm (1.57")	30 mm (1.18")	25 mm (0.98")
Feed rate	280 mm/min (11 ipm)	80 mm/min (3 ipm)	180 mm/min (7 ipm)	160 mm/min (7 ipm)	180 mm/min (7 ipm)	300 mm/min (12 ipm)
Cutting amount	140 cm ³ /min (8.5 in ³ /min)	64 cm ³ /min (3.9 in ³ /min)	144 cm ³ /min (8.8 in ³ /min)	160 cm ³ /min (9.8 in ³ /min)	162 cm ³ /min (9.9 in ³ /min)	225 cm ³ /min (13.7 in ³ /min)
Spindle motor load	93%	42%	80%	87%	94%	85%

Sample work pieces



Easy Operation

By the design of swivel operation panel and considerate splashguard of accessibility, the accessibility to spindle and pallet is significantly improved.



HM400 / HM500S

HM5100 / HM6000S
HM6300 / HM8000S

HM800 / HM1000S

Easy loading and unloading

Front door of the APC opens wide so that the work loading/unloading and setup operations can be carried out easily.



HM1000 / HM1250S

HM5100 / HM6000S

Easy Tool Loading and Unloading in Tool Magazine

1 Magazine interruption function

During automatic operation, the tool loading and unloading operation in the tool magazine can be executed.

2 Operation panel [Opt]

Through a simple operation, a tool corresponding to a designated tool number is called up to the setup position inside the magazine.

3 Foot-operated switch for removing a tool

The foot-operated switch eases removal of a tool from a magazine pot.



Operation Stand [Opt]



The operation stand is supplied optionally as needed.

*: Standard for HM1000/HM1250S

Photo is an example of operation stand.

Maintenance


Daily maintenance equipment is easily performed at the back and one side of machine.

HM400/50, HM500S/50



1 2 3 4

HM5100/HM6000S, HM6300/HM8000S



3 1 2 4

HM800/HM1000S



5 1 2 3 4 6 7

Daily maintenance equipment

No.	Name of equipment	No.	Name of equipment
1	Air regulator	5	Spindle oil-air unit
2	Air lubricator	6	Hydraulic unit
3	Air dryer	7	Oil temperature control unit for Spindle and screws
4	Oil -in-air removing unit		



Automatic lubrication unit for magazine and ATC part [Opt]



Automatic grease lubrication unit for linear guides and ball screws [Opt]

Eco friendly

ECO sleep function [Standard]

If the machine remains idle longer than the specified time period, the machine's present mode is switched to a power-saving mode to reduce wasteful consumption of power, air and so on. When the power-saving mode is active, the equipment such as servos and chip conveyors are turned off. It is cancelled automatically when the setup operation is completed i.e. when the doors are closed.

LED lamps

The machine incorporates LED lamps due to their low heat generation and power consumption savings. Furthermore, the LED lamps have a long life to save replacement money and maintenance.

Turning off lights inside the machine [Opt]

When the machine is not operated for a certain period of time, lights inside the machine are turned off automatically.




LED lamp work light

Easy return of ATC and APC

Tools and pallets can be returned easily to origin position in accordance with monitor, even if stopped at half way of ATC and APC.



Stopped at half way of ATC




Guidance display for ATC




ATC arm returned to origin position



Stopped at the half way of APC



Guidance display for APC





Pallet returned to origin position

Standard and optional Accessories

Item	Standard and optional Accessories						Standard	Option	Not available
	HM400/40 HM500S/40	HM400/50 HM500S/50	HM5100 HM6000S	HM6300 HM8000S	HM800 HM1000S	HM1000 HM1250S			
Controller	FANUC	FAi							
		F311							
		F311-B5	Essential for the 5-axis simultaneous control						
	Spindle taper and pull stud	Taper	BT40 BT50						
		Two faces contact holder	HSK-A63 HSK-A100						
Pull stud	BT type	OKK90°							
	MASi								
	MASii								
Maximum spindle speed	BT40	MS	10000min ⁻¹	37/26/22kW (50/35/30HP)					
			15000min ⁻¹	37/26/18.5kW (50/35/25HP)					
			20000min ⁻¹	37/26/18.5kW (50/35/25HP)					
	BT50	MS	8000min ⁻¹	55/37/30kW(74/50/40HP)					
				37/30kW (50/40HP)					
				22/18.5kW(30/25HP)					
	Gear	MS	12000min ⁻¹	30/25kW (40/34HP)					
				45/30/26kW (60/40/35HP)					
Table	IT(Index Table)	Least Index 1°							
	BRT(Built-in rotary table)	Least Index 0.001°						Least Index 0.0001°	
Addition of controlled axis									
Magazine	BT40	MSK-A63	40MG	40MG×1					
			60MG	60MG×1					
			80MG	80MG×1					
			120MG	62MG×2					
			156MG	80MG×2					
			178MG	62MG×3					
	BT50	MSK-A100	232MG	80MG×3					
			233MG/ 311MG/389MG	Matrix magazine					
			40MG	40MGX1					
			60MG	60MGX1	*2	*2	*2	*2	*2
			80MG	44MG+40MG					
			116MG	60MG×2	*2	*2	*2	*2	*2
			120MG	44MG+40MG×2					
			160MG	44MG+40MG×3					
		176MG	60MG×3	*2	*2	*2	*2	*2	
		236MG	60MG×4	*2	*2	*2	*2	*2	
233MG/ 311MG/389MG			Matrix magazine						
Magazine Interruption function									
Magazine operation panel									
Tool holder remove by foot pedal									
For Automatic pallet hanger and Pallet	APC	2-pallet APC							
		Multiple APC	6-pallet APC 8-pallet APC						
	Pallet	Tapped type Pallet T-Slot type Pallet Additional Pallet							
For Coolant and Chip conveyor	Coolant tank	Standard Coolant tank							
		Lift up chip conveyor	Hinged type/Scraper type/with Draum filter						
	Chip ejection	Coil conveyor	Bed left and right						
		Spindrecoolant nozzle							
	Collant	Ceiling Shower							
		Coolant shower gun							
		Air blow and oil mist							
		Coolant through spindle	2MPa (290psi)/7MPa (1015psi)						
		Air through spindle							
		Oil hole							
For accuracy	Dubble anchor pretension ball screw	With core cooling ball screw							
	Lubrication oil cooler unit								
	Linear scale feed back	XY-axis or XYZ-axis							
Other accessories	Signal tower lamp	Three lamp with buzzer	*4	*4	*4	*4	*4		
		LED light							
	Working light	Touch sensor T0	Manual measurement						
		Touch sensor T1-A	Workpiece automatic measurement						
	Tool length measurement and break detection	Touch sensor T1-B	Workpiece automatic measurement/ Tool length automatic measurement/ Tool break detection						
		Touch sensor T1-C	Tool length automatic measurement/ Tool break detection						
	Tool break detection	Tool break detection in magazine	Contact type or laser type						
	Automatic grease lubrication unit	XYZ -axis/ball screw							
	Automatic oil lubrication unit for MG and ATC part								
Foundation parts for machine anchoring	Bond anchoring method								
Rotary window	at operation door								

MG: Tool magazine unit
 Note 1: The separate setup station for the multiple APC is regarded as the standard specification when the multiple pallet specification is selected. (Except for HM400/500S and HM5100/HM6000S)
 *1: The controller needs to be changed when the 5-axis simultaneous control is selected.
 *2: It is not available for the HSK-A100.
 *3: Twenty-four M20s are used for HM1250S.
 *4: CE specification is optional.

High pressure coolant through spindle [Opt]



High pressure coolant unit

High pressure coolant is supplied to the tip of a cutting tool through the center hole of spindle and the cutting tool. It is very efficient for chip removal, cooling the cutting point and extending the life of cutting tools. Air supply through the spindle is also available by switching a valve. [Another Opt]



Thickener bag filter

Discharge pressure Mpa (psi)	2.0 (290)	7.0 (1,015)
	50Hz	36 (9.5) 21 (5.5)
Discharge volume L/min (gpm)	60Hz	35 (9.2) 30 (7.9)

Notes:
 *Discharge values indicated are at the outlet of pump.
 *Actual discharge volumes from the tool are different due to the hole-diameter of cutter tools.

Coolant shower gun [Opt]



Automatic lubrication unit for magazine and ATC part



Air blow nozzle [Opt]



Mist collector [Opt]*1



Mist collector suction mist from the splash guards and is recommended when high-pressure coolant is used.

Automatic grease lubrication unit for linear guides and ball screws



Oil mist & Air blow [Opt]




*1: We can provide the mounting holes in the splash guard and a terminal block for wiring in the control panel for the customer to install the equipment that the customer prepares for themselves.

For more stable machining accuracy


Coolant cooler [Opt]

Oil temperature has a major factor in thermal displacement of machine. Coolant cooler suppresses rise of temperature generated during machining and achieves a stable machining accuracy. This option is recommendable for accurate machining. This option is also strongly recommended, when the oil-based coolant is used.




Spindle

Dual-contact [Opt]



Improvements in rigidity of tools have been achieved by contact faces of spindle-nose and tool holders flange. This has a great effect not only for heavy load machining but also high speed machining. (The performance is different due to the cutting tools and cutting conditions.)




Stopper block [Opt]

- 1) For high speed spindle holder
- 2) For high speed spindle holder with coolant jacket
- 3) For angle head

Notes: Please inform OKK the brand name and model when you order this stopper block.

Type of pull stud

	7/24 taper No.40	7/24 taper No.50
OKK90°	Option	Standard
MASI	Standard	Option
MASII	Option	Option



Lift up chip conveyor [Opt]

Suitable lift up chip conveyor according to type of chips

⊙ Most suitable ○ Usable △ Usable under condition × Not usable - Not applicable

Type of chips	Type of chip conveyor	Hinge type		Scraper type		Magnet Scraper type		Scraper type with drum filter		Magnet scraper type with drum filter		
		Use	Not use	Use	Not use	Use	Not use	Use	Not use	Use	Not use	
Magnetizable chips	Steel	Short curl	⊙	⊙	○	○	⊙	⊙	○	-	⊙	-
		Spiral	⊙	⊙	△*2	△*2	△*2	△*2	×	-	×	-
		Long	⊙	⊙	×	×	×	×	×	-	×	-
		Needle shape	×	△*1	×	○	○*3	○	○	-	⊙	-
		Powder and small lump	×	△*1	×	○	○*3	○	○	-	⊙	-
		Cast iron	Needle shape	×	△*1	×	○	○*3	○	○	-	⊙
Powder and small lump	×		△*1	×	○	○*3	○	△*3	-	⊙	-	
Non-magnetizable chips	Aluminum	Short curl	×	⊙	△*4	○	-	-	⊙	-	⊙	-
		Spiral	○	⊙	○	○	-	-	△*5	-	△*5	-
		Long	○	⊙	○	○	-	-	△*5	-	△*5	-
		Needle shape	×	△*1	×	○	-	-	⊙	-	⊙	-
		Powder and small lump	×	△*1	×	○	-	-	⊙	-	⊙	-

- *1 Minute chips can enter the conveyor through a gap on the hinged plate. So, inside of the conveyor needs frequent cleaning.
- *2 Scraper can easily catch long chips. So, shortening the chips (for example by using the step feed) or removing such chips is required.
- *3 When flow rate of the coolant is large, filters can be clogged with chips flowed out of the conveyor case. Therefore, combined use with a magnet plate is recommendable.
- *4 When flow rate of the coolant is large, filters can be clogged with chips flowed out of the conveyor case. Therefore, filters require frequent cleaning.
- *5 Scraper can easily catch long chips. Therefore, periodical removal of chips is needed. If they remain, a drum filter may be damaged.

Height of chip drop

Type of chip conveyor	Hinged type, Scraper type and Magnet scraper type	Scraper type with drum filter	Magnet scraper type with drum filter
HM400/HM500S	1020 mm (40.16")	1100 mm (43.31")	1100 mm (43.31")
HM5100/HM6000S	1020 mm (40.16")	1220 mm (48.03")	1220 mm (48.03")
HM6300/HM8000S	1020 mm (40.16")	1220 mm (48.03")	1220 mm (48.03")
HM800/HM1000S	1070mm (42.13")	1200mm (47.24")	1200mm (47.24")
HM1000/HM1250S	1070mm (42.13")	1200mm (47.24")	1200mm (47.24")



Photo is Scraper type. Chip bucket is another option. There are fixed type and swivel type. Photo is fixed type chip bucket.

Magnet separator [Opt]



As an option for the lift-up chip conveyor, adding a magnet separator is possible for collecting powder and particle casting chips and preventing accumulation of chips inside tanks and clogging of devices such as pumps and filters.

Rotary wiper [Opt]



Install on operators window

Automatic measurement and Tool breakage detection with OKK Touch sensor system [Opt]

Model of touch sensor system

Function	Description	System name
Workpiece measurement and compensation	<ul style="list-style-type: none"> Load the touch sensor into the spindle. Automatic operations will bring the sensor into contact with the workpiece. The workpiece coordinate system will be measured and the necessary compensation amount will be updated. Program instructions are issued according to the specified format. 	T1-A
Tool length measurement	<ul style="list-style-type: none"> When a tool is commanded for tool length check, automatic operations will bring the tool in contact with the table mounted touch sensor. This operation will update the tool length offset for that tool. Measurement and compensation programs in accordance with the specified format are produced and executed. Applicable tools: Drills and taps 	T1-C
Tool break detection	<ul style="list-style-type: none"> When a tool is commanded for broken tool check, automatic operations will bring the tool in contact with the table mounted touch sensor. If the tool tip does not make contact with the sensor at the designated offset length the tool is determined to be broken. This checking command can be put into the machining program at any point. Applicable tools: Drills and taps Details of the movement when tool break is detected depend on the specifications of the machine main unit. 	T1-B

*Adding the T0 software enables also the manual measurement. Please refer to "T0 software [Opt]" on the page 29.

Tool length measurement and Tool breakage detection

A tool in the tool magazine is called up to the spindle, and length of the tool is measured automatically and registered automatically as data of the tool length in respective offset number. After the tool is used in machining, the tool can be checked for breakage automatically. If the tool is detected as damaged, the machine issues an alarm and stops operating.



Tool breakage detection in tool magazine [Another Opt]

This function enables detecting tool breakage in the tool magazine while the machine is in the automatic operation.



* Non contact type sensor of laser system is also available.

Type of sensor




[OMP60] Renishaw
Use the optical signal transfer method. The signal receiver block is not needed since signals are sent and received by using infrared rays. The signal receiver module can be fitted on inside wall of splash guard.



[RMP60] Renishaw
Use the radio signal transfer method. It is suitable for the machines having long distance for signal transfer from the sensor to the receiver such as the large models and 5-axis machining centers.

Manual measurement with software of touch sensor system T0

A sensor is moved to the desired measuring position by operating a manual handle. The machine starts measuring automatically when the sensor comes into contact with a workpiece, and results of the measurement are reflected in the settings of desired work coordinate system and tool offset number through a simple operation.



Hydraulic and compressed air supply ports for fixture [Opt]

Rotary joint on pallet system (Example 1)




Example of the use of 6-port rotary joint (HM400/500S, HM5100/6000S, HM6300/HM8000S, HM1000/1250S)

Supply from above the fixture: Hydraulic or air pressure can be applied to the clamping device constantly so that the workpiece clamping device is prevented from getting loose during machining. However, height of the fixture is limited due to a rotary joint and its piping installed above the fixture.

The pallet-through method is simple and does not require a rotary joint and its piping above the fixture. However, the clamp/unclamp function is available only in the setup station¹. (Hydraulic pressure and air pressure are not supplied after moving to the machining position.)

¹: Machine side is also possible only for HM6300/HM8000S. However, the APC side can have 4 ports on 4 systems and the machine side can have 4 ports on 1 system.

Rotary joint on pallet system (Example 2)



Example of the use of 3-port rotary joint (HM800/HM1000S)

Pallet through system (Use auto-coupler)





Photo with a fixture

Pallet through system (Use auto-coupler)

Fixture example




Multiple-pallet APC [Opt]

HM400/HM500S




With standard safety cover
HM400/HM500S




HM5100/HM6000S


[6-pallet with set-up station (pattern 1)]




[6-pallet with set-up station (pattern 2)]



[8-pallet with set-up station (pattern 1)]




[8-pallet with set-up station (pattern 2)]




HM6300/HM8000S


[6-pallet vertical type with set-up station]




[6-pallet horizontal type with set-up station]



[8-pallet vertical type with set-up station]




[8-pallet horizontal type with set-up station]




HM800/HM1000S


[6-pallet vertical type with set-up station]




[6-pallet horizontal type with set-up station]



[8-pallet vertical type with set-up station]




[8-pallet horizontal type with set-up station]




HM1000/HM1250S


[6-pallet horizontal type with set-up station]



[6-pallet vertical type with set-up station]



Auto restart function [Another Opt]



When a tool failure detected by a tool breakage detection system such as soft CCM, touch sensor system T1-C or others, automatic restart stops the machine and interrupts processing. The system will exchange the broken tool with an available spare tool then will either execute an APC or program end command.

OKK's exclusive control functions

Programming support functions

Program Editor [F31i-B]

Program editor allows you to edit programs stored in NC memory, from a data server (or hard disc) or memory card.



- Two programs can be displayed side by side.
- Characters in the program can be converted all at once. (Example: Changes F1000 to F1200.)
- Multiple-line data can be copied from other programs with ease.

- By switching the right-side screen for reference use, a list of M signals/G codes and information on tools in the magazine can be displayed.

- Programs can be copied or deleted and program names can be changed easily with the Program Editor.
- The Program Editor's multiple-file batch copy function enables to make a backup of the programs in the NC memory or hard disc easily with a memory card.

Setup support functions

Tool Support [F31i-B]

Now through a single set-up screen the tools number, description, schematic, and geometry are displayed. You can also perform the tool change commands and measurement cycle at the same set-up screen.

Tool setup screen



Tool length compensation amount measurement screen




T0 software [Opt]

This screen enables the simple manual measurement using the touch sensor (option: T1-A or T1-B). You can move the sensor to the desired measuring point by handle mode then the machine starts the automatic measurement after the sensor contacts the workpiece. You can set the results of the measurement as the data for the desired workpiece coordinate system and tool offset number through the single key operation.

Reference plane Coordinate rotation Distance



Width Diameter



Maintenance functions

Help Guidance [F31i-B]

The screen will display detailed information regarding the machine alarm and will explain how to recover the machine from the problem. This screen will also display a list of G-codes and a description of M signals.

Display of details of alarms



Description of M signals



Technologies for Reduced Setup and Unmanned Operation

Soft AC [Opt]

The soft AC function applies the feed rate override control automatically so that the value of the spindle load meter does not change significantly. This helps to prevent damages of tools caused by overload and improve cutting efficiency.

- Adaptive control function
 - Feed override control range: 10 to 200% (Changeable with parameters)
 - Alarms are output at the lower limit override value.
- Air-cut reduction function
 - Feed rates during non-cutting operation can be increased up to 200%. (Changeable with parameters)
- Tool failure monitoring function
 - Specifications similar to the soft CCM.
- Continuous unmanned machining at the time of tool failure (option)
 - Combined operation with the automatic restart function is possible.

Soft CCM [Opt]

The Soft CCM monitors the spindle load meter, and stops operation when the meter value exceeds the preset value (set by M signal or set for each of the T numbers through setting screen) and generation of abnormal tool load is determined which is convenient for unmanned operation at night.

High-efficiency Control Technologies

Hyper HQ Control [Opt]

High-speed processing is enabled by improved capability of processing fine line segment toolpaths.

F31i-B/FAi capability of processing fine line segments

Type	Fine line segment data processing speed (m/min)		Instruction method
	F31i-B	FAi	
Without Hyper HQ control	15 (591 ipm)		
Hyper HQ control mode A	30 (1181 ipm)		ON: G05.1Q1; OFF: G05.1Q0
Hyper HQ control mode B	150 (5906 ipm)	—	ON: G05.1Q1; OFF: G05.1Q0

The above values show (theoretical) maximum speeds for processing 1-mm-segment blocks constructing a straight line. Actual processing speeds depend on the type of the machine and NC data.

HQ Tuner [Opt]


The HQ tuner provides the programmer a 10-step adjustment of parameters for hyper HQ control in accordance with processing conditions. It adjusts the hyper HQ control in accordance with the current process. For example, during roughing routines the programmer can place a higher priority on speed and in finishing routines a higher priority on dimensional accuracy at corners and circular arcs.



High-efficiency Control Technologies

Data Server [Opt]

A large amount of machining programs can be transferred to the data server through the network connected to the host computer at high speed. The transferred machining programs are executed as the main programs or sub-programs (called up by using the M198 signal.)



FANUC Controller F31i-B Plus

(Windows CE-installed Open CNC)

Standard Specification
No. of controlled axes: 4 axes (X, Y, Z, B)
No. of simultaneously controlled axes: 3 axes(BRT specification is 4 axis)
Least input increment: 0.001mm / 0.0001" ※1
Least input increment: 0.001mm / 0.0001"(X,Y,Z) 0.0001deg(B(BRT)) ※2
Max. programmable dimension: ±999999.999mm / ±39370.0787"
Absolute / Incremental programming: G90 / G91
Decimal point input/Pocket calculator type decimal point input
Inch / Metric conversion: G20 / G21
Program code: ISO / EIA automatic discrimination
Program format: FANUC standard format
FS15 tape format
Nano interpolation (internal)
Positioning: G00
Linear interpolation: G01
Circular interpolation: G02 / G03 (CW/CCW)(Including radius designation)
Helical interpolation
Unidirectional positioning: G60
Cutting feed rate: 6.3-digit F-code, direct designation
Rapid traverse override: 0 / 1 / 10 / 25 / 50 / 100%
Cutting feed rate override: 0 to 200% (every 10%)
Feed rate override cancel: M49 / M48
Rigid tapping: G84, G74 (Mode designation: M29)
Manual handle feed:Least input increment ×1, ×10, ×100 / graduation
Dwell: G04
One-digit F code feed
inverse time feed
Part program storage capacity: total 10240m [4MB] (total 1000 programs)
Part program editing
Background editing: Possible to program or edit the machining program while NC machining is executed.
Extended part program editing
15-inch color LCD / QWERTY key MDI
Clock function
MDI (manual data input) operation
Run hour and parts count display
Memory card / USB interface
Spindle function: Direct designation of spindle speed with 5-digit S-code
Spindle speed override: 50 to 150% (every 5%)
Tool function: Direct designation of called tool number with 4-digit T-code
ATC tool registration
Auxiliary function: Designation with 3-digit M-code
Multiple M-codes in 1 block: Maximum 3 codes in 1 block (Maximum 20 settings)
Tool length offset: G43, G44 / G49
Tool diameter and cutting edge R compensation:G41, G42 / G40
Tool offset sets: total 400 sets
Tool offset memory C
Tool position offset
Automatic reference position return: G28 / G29
2nd reference position return: G30
Machine coordinate system: G53
Coordinate system setting: G92
Automatic coordinate system setting
Workpiece coordinate system: G54 to G59 G54.1 P1~P48
Local coordinate system: G52
Polar coordinate command: G15, G16
Manual reference position return
Reference position return check: G27
Optional block skip: /
Single block

Standard Specification
Dry run
Machine lock
Z-axis feed cancel
Auxiliary function lock
Graphic function
Program number search
Sequence number search
Program restart
Cycle start
Feed hold
Manual absolute (ON / OFF with PMC parameter)
Auto restart
Program stop: M00
Optional stop: M01
Sequence number collation and stop
Sub program control
Canned cycle: G73, G74, G76, G80 to G89
Mirror image function parameter
Custom macro
Programmable mirror image
Programmable data input: G10
Automatic corner override
Manual Guide i (Basic)
Exact stop check / mode
Scaling: G50, G51
Additional custom macro common variables:1000
Coordinate system rotation:G68,G69
Optional chamfering / corner R
Playback
Memory pitch error compensation (interpolation type)
Backlash compensation for each rapid traverse and cutting feed
Smooth backlash
Skip function
Tool life management: total 256 sets
Tool length manual measurement
Data protection key
NC alarm display / alarm history display
Machine alarm display
Stored stroke check 1
Stored stroke check 2
Load monitor
Self-diagnosis
Absolute position detection

Optional Specification
Additional one axes control:name of axis (A, C, U, V, W) ※3
Additional two axes control:name of axis (A, C, U, V, W) ※3
No. of simultaneously controlled axes: 5 axes ※3
Least input increment: 0.0001mm / 0.00001"
Spiral / Conical interpolation
Cylindrical interpolation
Hypothetical axis interpolation
Involute interpolation
NURBS interpolation
Smooth interpolation (Hyper HQ control B mode is required)
Handle feed 3 axes:Standard pulse handle is removed
Part program storage capacity: total 20480m [8MB] (1000 in total)
Machining time stamp

Optional Specification
Data server: ATA card (1GB)
Data server: ATA card (4GB)
RS232C interface: RS232C-1CH
Spindle contour control (Cs contour control)
Tool position offset
Tool offset sets: total 499 sets
Tool offset sets: total 999 sets
Addition of workpiece coordinate system (total 300 sets): G54.1 P1 to P300
Optional block skip: Total 9
Manual handle interruption
Tool retract and return
Figure copy
Interruption type custom macro
Instruction of inclined plane indexing
Chopping
Manual Guide i (Milling cycle)
Addition of tool life management sets: total 1024 sets
High-speed skip

Original Nidec OKK Software
Integrated machining support software (incl. help guidance, etc.) STD
Tool support STD
Program Editor STD
EasyPRO STD
Work Manager Opt
HQ control STD
Hyper HQ control mode A Opt
Hyper HQ control mode B Opt
Hyper HQ varue kit ※4 Opt
Special canned cycle (including circular cutting) Opt
Cycle Mate F Opt
Soft Scale II m STD
Touch sensor TO software Opt
Soft CCM (Tool failure detection system) Opt
Soft AC (Adaptive control unit) Opt
Automatic restart at tool damage Opt

※ 1: Excluding HM1000 / 1250S
 ※ 2: HM1000 / 1250S only
 ※ 3: F31i-B5 Plus (WindowsCE-installed Open CNC)
 ※ 4: Includes Data server: ATA card (1GB) and Hyper HQ control mode B

STD: Standard Opt: Option

FANUC Controller FAI

Standard Specification
No. of controlled axes: 4 axes (X, Y, Z, B)
No. of simultaneously controlled axes: 3 axes (4 axes for BRT specification)
Least input increment: 0.001mm / 0.0001"
Max.programmable dimension: ±999999.999mm / ±39370.0787"
Absolute / Incremental command: G90 / G91
Decimal point input / Pocket calculator type decimal point input
Inch / Metric conversion: G20 / G21
Program code: ISO / EIA automatic discrimination
Program format: FANUC standard format
Nano interpolation(internal)
Positioning: G00
Linear interpolation: G01
Circular interpolation: G02 / G03 (CW / CCW), including radius designation
Unidirectional positioning: G60
Helical interpolation
Cylindrical interpolation
Cutting feed rate: 6.3-digit F-code, direct command
Dwell: G04
Manual handle feed: manual pulse generator 1 set (0.001, 0.01, 0.1mm)
Rapid traverse override: 0 / 1 / 10 / 25 / 50 / 100%
Cutting feed rate override: 0 to 200% (every 10%)
Feed rate override cancel: M49 / M48
Rigid tapping: G84, G74 (Mode designation: M29)
One-digit F code feed
Inverse time feed
Part program storage capacity: 1280m[512KB]
No. of registered programs: 400
Part program editing
Background editing
Extended part program editing
10.4" color LCD
Clock function
MDI(Manual Data Input) operation
Run hour and parts count display
Memory card interface
Spindle function: 5-digit S-code direct command
Spindle speed override: 50 to 150% (every 5%)
Tool function: 4-digit T-code direct command
ATC tool registration
Auxiliary function: 3-digit M-code programming
Multiple M-codes in 1 block: 3 codes (Max. 20 settings)
Tool length offset: G43, G44 / G49
Tool diameter and cutting edge R compensation: G41, G42/G40
Tool offset sets: 400 sets in total
Tool offset memory C
Tool position offset
Manual reference position return
Automatic reference position return: G28/G29
2nd reference position return: G30
Reference position return check: G27
Automatic coordinate system setting
Coordinate system setting: G92
Machine coordinate system: G53
Workpiece coordinate system: G54 to G59
Local coordinate system: G52
Addition of workpiece coordinate system (48 sets in total): G54.1 P1 to P48
Program stop: M00
Optional stop: M01

Standard Specification
Optional block skip: /
Addition of optional block skip: 9 in total
Dry run
Machine lock
Z-axis feed cancel
Auxiliary function lock
Graphic display
Program number search
Sequence number search
Program restart
Cycle start
Auto restart
Single block
Feed hold
Manual absolute on / off: parameter
Sequence number comparison and stop
Manual handle interruption
Sub program control
Canned cycle: G73, G74, G76, G80 to G89
Mirror image function: parameter
Automatic corner override
Exact stop check/mode
Programmable data input: G10
Scaling: G50, G51
Custom macro
Interruption type custom macro
Addition of custom macro common variables: 600
Programmable mirror image
Coordinate system rotation: G68, G69
Optional chamfering / corner R
Manual guide i (Basic)
Backlash compensation for each rapid traverse and cutting feed
Memory pitch error compensation
Skip function
Tool length manual measurement
Tool life management: 128 sets in total
Emergency stop
Data protection key
NC alarm display / alarm history display
Machine alarm display
Stored stroke limit 1
Stored stroke limit 2, 3
Load monitor
Self-diagnosis
Absolute position detection

Optional Specification
Additional one axis control: name of axis (A, C, U, V, W) (No. of simultaneously controlled axes: 4 axes)
Additional two axes control: name of axis (A, C, U, V, W) (No. of simultaneously controlled axes: 4 axes)
FS11 tape format
Part program storage capacity: 5120m[2MB](400 in total)
Data server: ATA card (1GB)
Spindle contour control (Cs contour control)
Manual guide i (Milling cycle)
High-speed skip
RS232C interface: RS232C-1CH

STD: Standard Opt: Option

Standard Specifications

Item		HM400/40	HM500S/40	HM400/50	HM500S/50
Travel on X axis (Column: right/left)	mm	630 (24.80")			
Travel on Y axis (Spindle head: up/down)	mm	620 (24.41")			
Travel on Z axis (Table: back/forth)	mm	710 (27.95")			
Distance from table top surface to spindle center	mm	80-700 (3.15"-27.55")	50-670 (1.97"-26.38")	80-700 (3.15"-27.55")	50-670 (1.97"-26.38")
Distance from table center to spindle nose	mm	150-860(5.91"-33.86")			
Pallet work surface area	mm	□400 (15.75")	□500 (19.69")	□400 (15.75")	□500 (19.69")
Max. weight loadable on pallet	kg	(Uniform load) 450 (992lbs)			
Pallet top surface configuration		25×M16tap			
Minimum indexable angle of table	deg	BRT 0.001 / IT[Opt] 1°*			
Table index time (for indexing 90 degrees)	sec	BRT 0.5 / IT[Opt] 1.9			
Spindle speed	min ⁻¹	35-10,000		35-12,000	
Number of spindle speed change steps		Electric 2-step speed change (MS)			
Spindle inner taper		7/24 taper, No.40		7/24 taper, No.50	
Spindle bearing inner diameter	mm	ø80 (3.15")		ø100 (3.94")	
Rapid traverse rate	m/min	54 (2,126 ipm)			
Cutting feed rate	mm/min	1-40,000 (0.04-1574 ipm)*2			
Type of tool shank		JIS B 6339 BT40		JIS B 6339 BT50	
Type of pull stud		MAS403 P40T-1 (MASI)		OKK only 90°	
Tool storage capacity	tool	40*3			
Maximum tool diameter	mm	ø82 (3.23") / ø160 (6.30") without tool in adjacent pot		ø115 (4.53") / ø250 (9.84") without tool in adjacent pot	
Maximum tool length (from the gauge line)	mm	400 (15.75")			
Maximum tool weight	kg	12 (26 lbs) with slow ATC cycle		25 (55 lbs) with slow ATC cycle	
Maximum tool moment	N·m	9.8 (7.2 ft·lbs)		29.4 (21.7 ft·lbs)	
Tool selection method		Address fixed random system			
Tool change time (cut-to-cut)	sec	3.3		4.2	
Pallet change method		Direct turn			
Pallet change time (JIS evaluation time)	sec	9.5			
Spindle motor	AC, kW	FANUC 37 (50HP)/26 (35HP) / 22 (30HP) (25%ED/30min/cont. rating)		FANUC 30 (40HP) / 25 (34HP) (30min/cont. rating)	
Feed motor (X,Y,Z,B)	kW	FANUC 5.5 (7.4HP) / 5.5 (7.4HP) / 4.5 (6.0HP) /BRT: 4.5 (6.0HP) (IT[Opt]: 4.5 (6.0HP))			
Hydraulic pump motor	kW	1.5 (2.0HP)			
Motor of oil cooler for spindle and feed system (compression/discharge)	kW	1.1 (1.5HP) / 0.4 (0.5HP)			
Coolant pump motor	kW	50Hz: 0.7 (0.9HP) 60Hz: 1.2 (1.6HP)			
Power supply AC200V±10% 50/60±1Hz AC220V±10% 60±1Hz*4	kVA	FANUC 56		FANUC 62	
Compressed air supply	MPa, ℓ/min [ANR]	0.4-0.6*5, 500*6 (58-87 psi, 132 gal/min)			
Hydraulic unit tank capacity	ℓ	20 (5.3 gal)			
Spindle and feed system cooling oil tank capacity	ℓ	20 (5.3 gal)			
Coolant tank capacity	ℓ	720 (190 gal) (Option for the lift up type chip conveyor specification)			
Machine height	mm	2844 (111.97")		2970 (116.93")	
Required floor space	mm	Refer to the floor space drawing.			
Machine weight	kg	12,000 (26,455 lbs)	12,200 (26,896 lbs)	12,500 (27,557 lbs)	12,700 (27,998 lbs)
Operating environment temperature	°C	5-40			

*1 BRT: Built-in rotary table minimum indexing 0.001° IT: Index table minimum indexing 1°

*2 Available under the HQ or hyper HQ control.

*3 The number of stored tools refers a total number of tools including the one installed on the spindle i.e. subtract one from the above for actual number of tools stored in the tool magazine.

*4 When the supply voltage is 220VAC, the supply frequency of 60Hz only is applicable.


*5 Purity of compressed air should be class 3.5.4 or higher class of ISO 8573-1/JIS B8392-1 standard.

*6 Specified is the compressed air supply flow rate for standard specification machines. When optional specifications such as an air blow nozzle are added, add the corresponding air supply requirement.

Machine Dimensions


mm(in)

Floor Space




Front View

Lift up chip conveyor [Opt]




Pallet Dimensions



Pallet dimensions

	A	B	C	D
HM400	400(15.8")	50(1.97")	80(3.15")	130(5.12")
HM500S	500(19.7")	65(2.56")	100(3.94")	160(6.30")
HM400(T-slot)	400(15.8")	50(1.97")	80(3.15")	160(6.30")
HM500S(T-slot)	500(19.7")	65(2.56")	100(3.94")	190(7.48")


Restriction on Tool



XYZ axis travel diagrams

	A	B	C	D	E(BT40)	E(BT50)	F	G	H	I(BT40)	I(BT50)
HM400	400(15.75")	900(35.43")	700(27.56")	80(3.15")	95(3.74")	105(4.13")	200(7.87")	50(1.97")	110(4.33")	74(2.91")	76(2.99")
HM500S	500(19.69")	870(34.25")	670(26.38")	50(1.97")	166(6.54")	177(6.97")	250(9.84")	61(2.40")	90(3.54")	106(4.17")	106(4.17")
HM400(T-slot)	400(15.75")	870(34.25")	670(26.38")	50(1.97")	160(6.30")	160(6.30")	200(7.87")	50(1.97")	110(4.33")	150(5.91")	150(5.91")
HM500S(T-slot)	500(19.69")	840(33.07")	640(25.20")	20(0.79")	190(7.48")	190(7.48")	250(9.84")	61(2.40")	90(3.54")	150(5.91")	150(5.91")

XYZ axes travel diagrams



Dimensions and shape of workpiece:
 Blue-colored section: Dimensions and shape for HM400/40 and HM500S/40
 Red-colored section: Dimensions and shape for HM400/50 and HM500S/50
 Black-colored section: Dimensions and shape being common to the machines

Standard Specifications


Item		HM5100	HM6000S
Travel on X axis (Column: right/left)	mm	800 (31.50")	
Travel on Y axis (Spindle head: up/down)	mm	750 (29.53")	
Travel on Z axis (Table: back/forth)	mm	880 (34.65")	
Distance from table top surface to spindle center	mm	80~830 (3.15"~32.68")	50~800 (1.96"~31.50")
Distance from table center to spindle nose	mm	70~950 (2.76"~37.40")	
Pallet work surface area	mm	□ 500 (19.69")	□ 630 (24.80")
Max. weight loadable on pallet	kg	(Uniform load) 800 (1763 lbs)	(Uniform load) 700 (1543 lbs)
Pallet top surface configuration		24×M16tap	
Minimum indexable angle of table	°	BRT 0.001 / IT [Opt] 1**	
Table index time (for indexing 90 degrees)	sec	BRT 0.5 / IT [Opt] 1.7	
Spindle speed	min ⁻¹	35~12,000	
Number of spindle speed change steps		Electric 2-step speed change (MS)	
Spindle inner taper		7/24 taper, No.50	
Spindle bearing inner diameter	mm	ø100 (3.94")	
Rapid traverse rate	m/min	X,Z: 75 (2,953 ipm) Y: 60 (2,362 ipm)	
Cutting feed rate	mm/min	1~40,000 (0.04~1574 ipm)*2	
Type of tool shank		JIS B 6339 BT50	
Type of pull stud		OKK only 90°	
Tool storage capacity	tool	60*3	
Maximum tool diameter	mm	ø115 (4.53") / ø300 (11.81") without tool in adjacent pots	
Maximum tool length (from the gauge line)	mm	600 (23.62")	
Maximum tool weight	kg	When turning at normal speed: 10; When slow turning is selected: 30	
Maximum tool moment	N·m	29.4 (21.68 ft·lbs)	
Tool selection method		Address fixed random system	
Tool change time (cut-to-cut)	sec	3.6	
Pallet change method		Direct turn	
Pallet change time (JIS evaluation time)	sec	10	
Spindle motor (25%ED/30min/cont. rating)	AC, kW	FANUC 45 (60HP) / 30 (40HP) / 26 (35HP)	
Motor for ATC (Automatic Tool Changer)	kW	1.5 (2HP)	
Feed motor (X,Y,Z,B)	kW	FANUC 5.5 (7.4HP) / 5.5 (7.4HP) / 5.5 (7.4HP) / BRT: 4.5 (6.0HP) (IT[Opt]: 2.7 (3.6HP))	
Hydraulic pump motor	kW	1.5 (2HP)	
Motor of oil cooler for spindle and feed system (compression/discharge)	kW	1.1 (1.5HP) / 0.4 (0.5HP)	
Coolant pump motor	kW	50Hz: 0.7 (0.9HP) 60Hz: 1.2 (1.6HP)	
Power supply AC200V±10% 50/60±1Hz AC220V±10% 60±1Hz*4	kVA	FANUC 58	
Compressed air supply	MPa, ℓ/min [ANR]	0.4~0.6*5, 500*6 (58~87 psi, 132 gal/min)	
Hydraulic unit tank capacity	ℓ	20 (5.3 gal)	
Spindle and feed system cooling oil tank capacity	ℓ	20 (5.3 gal)	
Magazine lubricating oil tank capacity	ℓ	4 (1.1 gal)	
Coolant tank capacity	ℓ	720 (190 gal) (Option for the lift up type chip conveyor specification)	
Machine height	mm	4115 (162")	
Required floor space	mm	4,980×5,380 (196.06"×211.81") (Option for the lift up type chip conveyor specification)*7	
Machine weight	kg	15,700 (34,612 lbs)	16,000 (35,273 lbs)
Operating environment temperature	°C	5~40	

*1 BRT: Built-in rotary table minimum indexing 0.001° IT: Index table minimum indexing 1°
 *2 Available under the HQ or hyper HQ control.
 *3 The number of stored tools refers a total number of tools including the one installed on the spindle i.e. subtract one from the above for actual number of tools stored in the tool magazine.
 *4 When the supply voltage is 220VAC, the supply frequency of 60Hz only is applicable.
 *5 Purity of compressed air should be class 3.5.4 or higher class of ISO 8573-1/JIS B8392-1 standard.
 *6 Specified is the compressed air supply flow rate for standard specification machines. When optional specifications such as an air blow nozzle are added, add the corresponding air supply requirement.
 *7 Includes door opening dimensions


Machine Dimensions

mm(in)


Floor Space



Front View



Pallet Dimensions



	A	B	C	D
HM5100	500(19.69")	60(2.36")	100(3.94")	130(5.12")
HM6000S	630(24.80")	70(2.76")	125(4.92")	160(6.30")


Notes: Tap and T-slot are same dimensions.

	A	B	C	D	E
HM5100	500(19.69")	1330(52.36")	830(32.68")	80(3.15")	334(13.15") ¹
HM6000S	630(24.8")	1300(51.18")	800(31.5")	50(1.97")	420(16.54") ²


¹ At B-axis rotated 0°/90°/180°/270°: 250mm (9.84").
² At B-axis rotated 0°/90°/180°/270°: 315mm (12.40").

Notes: Tap and T-slot are same dimensions.

Restriction on Tool



XYZ axes travel diagrams



Standard Specifications

Item		HM6300	HM8000S
Travel on X axis (Column: right/left)	mm	1050 (41.34")	
Travel on Y axis (Spindle head: up/down)	mm	900 (35.43")	
Travel on Z axis (Table: back/forth)	mm	1030 (40.55")	
Distance from pallet top surface to spindle center	mm	80~980 (3.15"~38.58")	60~960 (2.36"~37.80")
Distance from pallet center to spindle nose	mm	50~1080 (1.97"~42.52")	
Pallet work surface area	mm	□ 630 (24.80")	□ 800 (31.50")
Max. weight loadable on pallet	kg	(Uniform load) 1500 (3307 lbs)	(Uniform load) 1400 (3086 lbs)
Pallet top surface configuration		24xM16 tap	
Minimum indexable angle of table	°	BRT: 0.001°*	
Table index time (for indexing 90 degrees)	sec	BRT: 0.6	
Spindle speed	min ⁻¹	35~12,000	
Number of spindle speed change steps		Electric 2-step speed change (MS)	
Spindle inner taper		7/24 taper, No.50	
Spindle bearing inner diameter	mm	ø100 (3.94")	
Rapid traverse rate	m/min	X,Z 75 (2953 ipm) Y 54 (2126 ipm)	
Cutting feed rate	mm/min	1~40,000 (0.04~1574 ipm)**	
Type of tool shank		JIS B 6339 BT50	
Type of pull stud		OKK 90°	
Tool storage capacity	tool	60*3	
Maximum tool diameter	mm	ø115 (4.53") / ø300 (11.81") without tool in adjacent pots	
Maximum tool length (from the gauge line)	mm	600 (23.62")	
Maximum tool weight	kg	When turning at normal speed: 10 (22 lbs); When slow turning is selected: 30 (66.1 lbs)	
Maximum tool moment	N·m	29.4 (21.7 ft·lbs)	
Tool selection method		Address fixed random system	
Tool change time (cut-to-cut)	sec	4.0	3.9
Pallet change method		Direct turn	
Pallet change time (JIS evaluation time)	sec	15.0	
spindle motor (25%ED/30min/cont. rating)	AC, kW	45 (60HP) / 30 (40HP) / 26 (35HP)	
Motor for ATC (Automatic Tool Changer)	kW	1.5 (2.0 HP)	
Feed motor (X, Y, Z, B)	kW	5.5 (7.4 HP) / 5.5 (7.4HP) / 5.5 (7.4 HP) / BRT: 5.5 (7.4 HP)	
Hydraulic pump motor	kW	1.5 (2.0 HP)	
Motor of oil cooler for spindle and feed system (compression/discharge)	kW	1.1 (1.5 HP) / 0.4 (0.5 HP)	
Coolant pump motor	kW	50Hz: 0.75 (1.0 HP) 60Hz: 1.1 (1.5 HP)	
Motor for APC unit	kW	0.75 (1.0 HP)	
Power supply 200VAC ±10% 50/60 ±1Hz 220VAC ±10% 60 ±1Hz ⁴	kVA	60	
Compressed air supply	MPa, ℓ/min [ANR]	0.4~0.6 ⁵ , 500 ⁶ (58~87 psi, 132 gal/min)	
Hydraulic unit tank capacity	ℓ	20 (5.3 gal)	
Spindle and feed system cooling oil tank capacity	ℓ	20 (5.3 gal)	
Magazine lubricating oil tank capacity	ℓ	4.0 (1.1 gal)	
Coolant tank capacity	ℓ	720 (190 gal) (Option for the lift up chip conveyor specification)	
Machine height	mm	4115 (162.01")	
Required floor space	mm	5250~5825 (206.69"~x229.33") (Option for the lift up chip conveyor specification)	
Machine weight	kg	18,500 (40784.8 lbs)	18,800 (41446.2 lbs)
Operating environment temperature	°C	5~40	

*1 BRT: Built-in rotary table minimum indexing 0.001°

*2 Available under the HQ or hyper HQ control.

*3 The number of stored tools refers a total number of tools including the one installed on the spindle i.e. subtract one from the above for actual number of tools stored in the tool magazine.

*4 When the supply voltage is 220VAC, the supply frequency of 60Hz only is applicable.


*5 Purity of compressed air should be class 3.5.4 or higher class of ISO 8573-1/JIS B8392-1 standard.

*6 Specified is the compressed air supply flow rate for standard specification machines. When optional specifications such as an air blow nozzle are added, add the corresponding air supply requirement.


Dimensions

mm(in)


Floor Space



Front View



Pallet Dimensions



Pallet dimensions

	A	B	C	D
HM6300	630(24.8")	70(2.76")	125(4.92")	160(6.30")
HM8000S	800(31.5")	100(3.94")	160(6.30")	180(7.09")
HM8000S(T-slot)	800(31.50")	100(3.94")	160(6.30")	200(7.87")


HM6300: Tap and T-slot are same dimensions.

XYZ axis travel diagrams


	A	B	C	D	E	F
HM6300	630(24.8")	1300(51.16")	980(38.58")	80(3.15")	315(12.40")	85(3.35")
HM8000S	800(31.5")	1280(50.39")	960(37.80")	60(2.36")	400(15.75")	100(3.94")
HM8000S(T-slot)	800(31.50")	1260(49.61")	940(37.01")	40(1.57")	400(15.75")	100(3.94")

HM6300: Tap and T-slot are same dimensions.

Restriction on Tool



XYZ axes travel diagrams



(Note 1)
For executing the APC operation, the loaded workpiece must not exceed the specified maximum APC turning diameter.

□ Interference range of X/Y-axis shutter and workpiece

Standard Specifications


Item		HM800	HM1000S
Travel on X axis (Column: right/left)	mm	1400 (55.12")	
Travel on Y axis (Spindle head: up/down)	mm	1100 (43.31")	
Travel on Z axis (Table: back/forth)	mm	1050 (41.34")	1000 (39.37")
Distance from pallet top surface to spindle center	mm	60-1160 (2.36"-45.67")	30-1130 (1.18"-44.49")
Distance from pallet center to spindle nose	mm	200-1250 (7.87"-49.21")	250-1250 (9.84"-49.21")
Pallet work surface area	mm	□ 800 (31.50")	□ 1000 (39.37")
Max. weight loadable on pallet	kg	(Uniform load) 2000 (4400 lbs)	(Uniform load) 2500 (5500 lbs)
Pallet top surface configuration		24xM16 tap	
Minimum indexable angle of table	°	BRT 0.001/IT[Opt] 1 **	
Table index time (for indexing 90 degrees)	sec	BRT 1.2 / IT [Opt] 4.5	BRT 1.2 / IT [Opt] 5.5
Spindle speed	min ⁻¹	35-12,000	
Number of spindle speed change steps		Electric 2-step speed change (MS)	
Spindle inner taper		7/24 taper, No.50	
Spindle bearing inner diameter	mm	ø100 (3.94")	
Rapid traverse rate	m/min	48 (1,889 ipm)	
Cutting feed rate	mm/min	1-40,000 (0.04-1574 ipm)**	
Type of tool shank		JIS B 6339 BT50	
Type of pull stud		OKK 90°	
Tool storage capacity	tool	60*3	
Maximum tool diameter	mm	ø115 (4.53") / ø270 (10.63") without tool in adjacent pots	
Maximum tool length (from the gauge line)	mm	500 (19.69")	
Maximum tool weight	kg	25 (55 lbs)	
Maximum tool moment	N·m	29.4 (21.7 ft·lbs)	
Tool selection method		Address fixed random system	
Tool change time (cut-to-cut)	sec	5.8	
Pallet change method		Direct turn	
Pallet change time (JIS evaluation time)	sec	19.0	21.0
spindle motor (30min/cont. rating)	AC, kW	30 (40HP) / 25 (34HP)	
Motor for tool clamp/unclamp unit	kW	0.75 (1.0HP)	
Feed motor (X, Y, Z, B)	kW	5.5 (7.4HP) / 9.0 (12.1HP) / 6.0 (8.0HP) / BRT 4.5 (6.0HP) (IT[Opt] 2.7 (3.6))	
Hydraulic pump motor	kW	1.5 (2.0HP)	
Motor of oil cooler for spindle and feed system (compression/discharge)	kW	1.7 (2.3HP) / 0.75 (1.0HP)	
Coolant pump motor	kW	50Hz: 0.75(1.0HP) 60Hz: 1.1(1.5HP)	
Motor for APC unit	kW	0.75 (1.0HP)	
Power supply 200VAC ±10% 50/60 ±1Hz 220VAC ±10% 60 ±1Hz ⁴	kVA	61	
Compressed air supply	MPa, ℓ/min [ANR]	0.4-0.6 ⁵ , 500 ⁶ (58-87 psi, 132 gal/min)	
Hydraulic unit tank capacity	ℓ	20 (5.3 gal)	
Spindle and feed system cooling oil tank capacity	ℓ	70 (18 gal)	
Magazine lubricating oil tank capacity	ℓ	4.0 (1.1 gal)	
Coolant tank capacity	ℓ	1520 (402gal) Option for the lift up chip conveyor specification	
Machine height	mm	4336 (170.71")	
Required floor space	mm	5147 (202.64") x 6785 (267.13") Option for the lift up chip conveyor specification	
Machine weight	kg	24,500 (54,000 lbs)	25,000 (55,000 lbs)
Operating environment temperature	°C	5-40	

*1 BRT: Built-in rotary table minimum indexing 0.001° IT: Index table minimum indexing 1°
 *2 Available under the HQ or hyper HQ control.
 *3 The number of stored tools refers a total number of tools including the one installed on the spindle i.e. subtract one from the above for actual number of tools stored in the tool magazine.
 *4 When the supply voltage is 220VAC, the supply frequency of 60Hz only is applicable.
 *5 Purity of compressed air should be class 3.5.4 or higher class of ISO 8573-1/JIS B8392-1 standard.
 *6 Specified is the compressed air supply flow rate for standard specification machines. When optional specifications such as an air blow nozzle are added, add the corresponding air supply requirement.


Dimensions

mm(in)


Floor Space




Front View



Pallet Dimensions



Restriction on Tool



Pallet dimensions

	A	B	C	D
HM800	800(31.5")	100(3.94")	160(6.30")	174(6.85")
HM1000S	1000(39.37")	125(4.92")	200(7.87")	204(8.03")
HM800(T-slot)	800(31.5")	100(3.94")	160(6.30")	204(8.03")
HM1000S(T-slot)	1000(39.37")	125(4.92")	200(7.87")	214(8.43")

XYZ axis travel diagrams

	A	B	C	D	E	F	G	H	I	J	K	L	M
HM800	800(31.5")	200(7.87")	1050(41.34")	1050(41.34")	200(7.87")	1300(51.18")	1160(45.67")	60(2.36")	305(12.01")	400(15.75")	100(3.94")	105(4.13")	109(4.29")
HM1000S	1000(39.37")	250(9.84")	1000(39.37")	1000(39.37")	250(9.84")	1270(50.00")	1130(44.49")	30(1.18")	392(15.43")	500(19.69")	125(4.92")	142(5.59")	140(5.51")
HM800(T-slot)	800(31.5")	200(7.87")	1050(41.34")	1050(41.34")	200(7.87")	1270(50.00")	1130(44.49")	30(1.18")	317(12.48")	400(15.75")	100(3.94")	105(4.13")	140(5.51")
HM1000S(T-slot)	1000(39.37")	250(9.84")	1000(39.37")	1000(39.37")	250(9.84")	1260(49.61")	1120(44.09")	20(0.79")	392(15.43")	500(19.69")	125(4.92")	142(5.59")	150(5.91")

XYZ axes travel diagrams

